





Injection molding process window



































Melt Delivery


A sprue is a channel through which to transfer molten plastics injected from the injector nozzle into the mold.


A runner is a channel that guides molten plastics into the cavity of a mold.

A gate is an entrance through which molten plastics enters the cavity.

39

Gate -Delivers the flow of molten plastics. -Quickly cools and solidifies to avoid backflow after molten plastics has filled up in the cavity. -Easy cutting from a runner -Location is important to balance flow and orientation and to avoid defects.





Gate Positioning


Point 1: Set a gate position where molten plastics finish filling up in each cavity simultaneously. Same as multiple points gate.


Point 2: Set a gate position to the thickest area of a part. This can avoid sink marks due to molding (part) shrinkage .

Point 3: Set a gate position to an unexposed area of part or where finishing process can be easily done.

Point 4: Consider weldline, molecular orientation.

2.008 spring 2004 S. Kim





42

Defects

2.008 spring 2004 S. Kim

Molding defects are caused by related and complicated reasons as follows:

- * Malfunctions of molding machine
- * Inappropriate molding conditions
- * Flaws in product and mold design
- * Improper Selection of molding material

Weldline



46

Weid The This is a phenomenon where a thin line is created when different flows of molten plastics in a mold cavity meet and remain undissolved. It is a boundary between flows caused by incomplete dissolution of molten plastics. It often develops around the far edge of the gate.


Cause


Low temperature of the mold causes incomplete dissolution of the molten plastics.

Solution

Increase injection speed and raise the mold temperature. Lower the molten plastics temperature and increase the injection pressure. Change the gate position and the flow of molten plastics. Change the gate position to prevent development of weldline.

2.008 spring 2004 S. Kim





Warpage



49

This deformation appears when the part is removed from the mold and pressure is released.

Cause

Uneven shrinkage due to the mold temperature difference (surface temperature difference at cavity and core), and the thickness difference in the part. Injection pressure was too low and insufficient packing.

Solution

2.008 spring 2004 S. Kim

Take a longer cooling time and lower the ejection speed. Adjust the ejector pin position or enlarge the draft angle. Examine the part thickness or dimension. Balance cooling lines. Increase packing pressure.

