


Assembly and Joining


1

Manufacture



2


Impact of Design on Product Cost



The majority of cost commitment is made early in the **product design cycle**

3

Cost of Design Changes



4

“The best design is the
simplest one that works”

Albert Einstein

5

Assembly and Joining

- Assembly as a mfg process
 - Process components
 - Cost, Quality, Rate and Flexibility
- Specific joining processes
 - Mechanical
 - Adhesives
 - Solder and brazing
 - Cold welding
 - Fusion welding

6

Assembly statistics

Industry	% Workers in Assembly
Automobile	45.6%
Aircraft	25.6%
Telephone & Telegraph	58.9%
Farm Machinery	20.1%
Home appliances	32.1%
Two-wheel vehicles	26.3%


7

Justifying the need/type of assembly

- For assembly
 - Can't be made in one piece
 - Functional (bushings, bearings)
 - Manufacturability
 - Repair and maintenance
 - Transport: Does it fit in a plane?
- Against assembly
 - Defects that occur at interfaces
 - Loss of stiffness
 - Time & effort
 - Labor costs
 - Size

8

Rough assembly process diagram



9

Manual vs Automatic Assembly

- **Manual assembly**
 - Dexterity
 - Time (small run, urgent)
 - Complexity
- **Automatic assembly**
 - Precision
 - Load
 - Time
- **What is important**
 - Minimize parts
 - Ergonomics
 - Cost
 - Training
 - Reliability

10

PART TRANSPORT, ORIENTATION AND FEEDING

11

Part handling and feeding

- Moving parts between processing stations
- Control amount delivered
- Control spacing and frequency of delivery
- Robust with respect to tangling and jamming

12

Part transport: Overhead



<http://www.tegopi.pt/novidades/images/25-10-2000.jpg>



[http://accosystems.com/autoclient%20\(2\).jpg](http://accosystems.com/autoclient%20(2).jpg)

13

Part transport: Conveyor




<http://www.ssiconveyors.com/pics/>



<http://www.ssiconveyors.com/pics/>


14

Part transport: Transfer line




15

AGV




16

Part feeding and orientation




17

Part feeding and orientation




18

Part feeding and orientation



19

Part feeding and orientation



20


Guidelines to Good Design-for-Assembly

- Minimize the number of parts
- Design assembly process in a layered fashion
- Consider ease of part handling
- Utilize optimum attachment methods
- Consider ease of alignment and insertion
- Avoid design features that require adjustments

21

DFA - Example


Minimize the number of parts



22

DFA - Example


Minimize the number of parts



23

DFA - Example


Design assembly process in a layered fashion



24

DFA - Example


Consider ease of part handling



25

DFA - Example


Consider ease of part handling



26

DFA - Example



Utilize optimum attachment methods



27

DFA - Example


Utilize optimum attachment methods



28

DFA - Example


Utilize optimum attachment methods



29

DFA - Example

Utilize optimum attachment methods




30

DFA - Example

Consider ease of alignment and insertion

- Design parts to maintain location




31

DFA - Example

Consider ease of alignment and insertion


- Mating parts should be easy to align and insert



32

DFA - Example


Consider ease of alignment and insertion



33

DFA - Example


Avoid design features that require adjustments



34

DFA - Example

Avoid restricted vision



35

DFA - Example

Avoid obstructed access




36

Joining

- Assembly cost often account for more than 50%
- Joining processes
 - High scrap cost
 - Failure spot

37

Joining processes/types



38

Selection Criteria

- Geometry
- Material type
- Value of end product
- Size of product run
- Availability of joining method

39

MECHANICAL JOINING

40

Mechanical Fastening

- Any shape and material
- Semi-permanent
- Least expensive for low volume (standardized)
- Problems: strength, seal, extra part, assembly, loosen

41

Fasteners

- Bolts/screws
 - Good for disassembly and reassembly
 - Cross threading can be a problem
- Rivets
 - Used when disassembly is not required
- Dowel pins
- Cotter pins
- Snap fits


42

Common alignment mechanisms


Relative cost:
 \$ = low cost
 \$\$ = moderate cost
 \$\$\$ = expensive



Elastic Averaging
Non-Deterministic



Pinned Joints
No Unique Position




Exact constraint
Kinematic Constraint

Contaminants:	Sensitive	Contaminants:	Insensitive	Contaminants:	Insensitive
Load capacity:	High	Load capacity:	Low - High	Load capacity:	Low - High
Wear in:	Long	Wear in:	No	Wear in:	Short
Exact constraint:	No	Exact constraint:	No	Exact constraint:	Yes
Cost:	\$\$\$	Cost:	\$ <-> \$\$\$	Cost:	\$\$
Complexity:	Simple	Complexity:	Simple	Complexity:	Moderate
Common:	Yes	Common:	Yes	Common:	No
Repeatability ~	5 micron after wear in	Repeatability ~	25 micron at best	Repeatability ~	¼ micron 43 is common

Embossing and hemming

- Embossed protrusions
 - Plastic deformation / interference
 - Appliances
 - Automotive
 - Furniture
- Hemming
 - Bend edge of one component over another
 - Automobile doors



44



Press fits

δ = radial interference
 E = Young's modulus
 p = interface pressure

α = Coefficient of thermal expansion
 ΔT = Temperature change

$$p = \frac{E}{R} \cdot \delta \cdot \left[\frac{(r_o^2 - R^2) \cdot (R^2 - r_i^2)}{2 \cdot R^2 \cdot (r_o^2 - r_i^2)} \right] \rightarrow F_{insert} = \mu \cdot p \cdot 2 \cdot \pi \cdot R \cdot x_{insert}$$

$$\delta_{thermal} = \alpha \cdot R \cdot \Delta T$$



45

ADHESIVE JOINING

46

Example – Adhesive Bonding



47

Adhesive joining

- Advantages
 - Different materials, Easily automated, Damp /seal
- Limitations
 - Time, Preparation/curing, Loading
- Important properties/characteristics of adhesives
 - Strength, Chemically inert, Compatibility


48

Adhesive Bonding

- Quick, non-invasive, inexpensive
- Low stress
- Variety of materials
- Seal
- Low part count
- Temperature-limited
- Long set time
- Surface preparation
- Reliability/disassembly
- Best for components with high surface to volume ratio

49

Stefan Equation



$$Ft = \frac{3\mu\pi a^4}{4} \left[\frac{1}{h_f^2} - \frac{1}{h_i^2} \right]$$

50

What does Stefan equation mean?

$$F \cdot t_{final} \approx \frac{3 \cdot \mu \cdot \pi \cdot a^4}{4} \cdot \left(\frac{1}{h_{final}^2} \right)$$


Viscosity: Start with low μ & finish with high μ

Gap: Small assembled gap

51

DFM with adhesives

- What is important
 - Matching type of loading to the design (shear/tension vs. peeling)
 - Maximizing contact area




52

BRAZING & SOLDERING

53

Example – Brazing / Soldering



54

Soldering/Brazing

- Capillary
- Shear strength
- Temperature limit
 - Soldering : < 450 degree : Lead, Tin
 - Brazing : > 450 degree: Silver, Brass, Bronze
- Substrate phase stays solid : can be used on dissimilar metals
- Used in electronics, plumbing, jewelry, and recently, as a structural joining

55

Soldering & brazing

- Brazing: $T > 450^{\circ}\text{C}$
 - Brazes: Silver, Brass, Bronze
- Soldering: $T < 450^{\circ}\text{C}$
 - Low temps require fluxes
 - Solders: Lead, Tin, Bismuth



- Processes
 - Torch: Oxyacetylene torch and filler metal
 - Furnace: Lay filler around joint and send into furnace
 - Induction: Heat part by induction
 - Resistance: Heat part by contact/current

56


Anatomy of solder/brazing process

•Purpose of fluxes

- Remove oxides
- Protect from oxidization
- Improve surface wetting

•Process


- A. Flux on top of oxidized metal
- B. Boiling flux removes oxide
- C. Base metal in contact with molten flux
- D. Molten solder displaces molten flux
- E. Solder adheres to base metal
- F. Solder solidifies



57

DFA for Soldering and Brazing

- Provide large surface area contact
- Filler metal should have good wetting characteristics (capillary action)
- Joined surfaces should not be smooth




58

COLD WELDING (Interatomic) PROCESSES

59

Ultrasonic and friction welding


- Ultrasonic welding (shear @ 10 to 75kHz vibration)
 - Contamination is redistributed, not displaced
 - Example: Wires/connectors in electronics components
- Friction welding
 - Material surfaces sheared against each other
 - Some metal extrudes out of weld zone, removes contaminates



60

Diffusion bonding

- Diffusion bonding is often divided into three stages
 - Asperities + pressure = decreased interface porosity
 - Continued heating causes the porosities to shrink
 - Crystals grow across interface, some porosity may be trapped
- Time: Important variables/parameters:
 - Pressure = (500 to 5,000 psi)
 - Temperature ($\frac{2}{3} T_{\text{melt}}$)
 - Surface finish
 - Surface cleanliness




61

FUSION WELDING PHYSICS

62


Example – Spot Welding



63

Fusion welding

- Process of fusing two materials to join them
- Challenges in fusion welding
 - Disrupting oxide layers and contamination



- Achieving high % surface area contact



64


Welding

- Heat source
- Heat intensity
 - Control (overmelting/evaporation)
 - Heat affected zone (HAZ)
 - Efficiency
 - Depth/width ratio

65

Heat Intensity

- A measure of radiation intensity, W/cm²



- Obviously the more intense the source, the faster the melting
- Very difficult to prevent overmelting, therefore **automation!**

66

Heat intensity and interaction time

- Heat intensity (in W/cm²)
 - HI = Power per unit area directed into the welding zone
 - HI ~10³ melting in < 25 seconds
 - HI ~10⁶ vaporizes metal in μseconds
- Propagation of heat in solids: $x \sim (\alpha \cdot t)^{0.5}$
 - x = distance thermal disturbance travels into thick slab
 - t = elapsed time

	ρ g/cm ³	k W/m/K	c_p J/g/oC	α cm ² /s	t_{melt} oC	t_{melt} oF
Aluminum	2.7	200	0.890	0.832	660	1220
Copper	8.9	400	0.385	1.167	1085	1985
1020 steel	7.9	50	0.448	0.141	1500	2732
Delrin	1.4	0.36	1.464	0.002	175	347


67

Weld pool from 2D simplification

The Jacob number, $J_a = c_p \frac{(T_{melt} - T_{initial})}{h_{fs}}$.

The thermal diffusivity is given by $\alpha = \frac{k}{\rho c_p}$.

The melt front moves as: $s = \sqrt{2\alpha J_a t}$



68

Welding Rate


The rate at which the welding device must be moved is governed by:

- The **Heat Intensity** - the greater the intensity, the faster the motion must be to keep the weld pool size, s_{max} , constant
- The product, αJ_a , The greater it is, the faster the melt front moves

69

Welding Rate (cont.)

- In fact, the time at a spot, t_{max} is given by $s_{max}^2 / 2\alpha J_a$. Anymore, and you over-melt!



- If the weld pool size is d in length, then you must feed at a rate that exceeds d/t_{max} . Similarly a lower limit.

70

Melting front and welding velocity


- Definitions of Jacob # and thermal diffusivity:

$$J = c_p \cdot \frac{T_{melt} - T_{initial}}{h_{fs}} \quad \alpha = \frac{k}{\rho \cdot c_p}$$

- Solidification front moves in "s" direction as:



- To maintain constant weld pool depth at s



71


Welding Rate (cont.)

- For a planar heat source on steel,

$$t_m = (5000/H.I.)^2$$
 : where H.I. is the heat intensity in W/cm^2 . The number 5000 includes the material constant related terms.
- Clearly the greater the H.I. The faster the metal melts.

72


Weld Pool – Heat Source Interaction Time



Main factor : Thermal diffusivity

73


Weld Travel Velocity



74

Heat Affected Zone

- Region near the weld pool is affected by heat. Microstructure changes.




- The size of the heat affected zone is controlled by the thermal diffusivity, α .

75

Heat Localization

- Why does alpha affect the size of the HAZ?



- Lower values of alpha, more localized heating, which is better for welding?
- Have you tried taking a soldering iron to plastic? You get small weld pool. But on metal, you heat the whole piece!


76

FUSION WELDING PROCESSES

77

Oxyfuel gas welding



- Air/fuel welding
 - Low-cost, portable and flexible
 - Oxidizing and reducing flames



78

General arc welding



- Voltage difference between electrode & work piece
 - Voltage ~ 100 - 500 V
 - Current ~ 50 - 300 A
- Electrode may be consumed



79

Fillers and shielding in arc welding


- Filler metals
 - Adds metal to weld zone
 - Flux on/in filler cleans/prevents oxidization
 - Slag protects molten puddle from oxidization
- Shielding
 - Pellets or grains
 - Gaseous



80


General resistance welding

- High current through weld area (3k – 40k Amps)
 - Important: contact pressure & weld current & weld time
 - Simple, reliable fusion processes
 - Welds often not easy to inspect (i.e. spot welds)
 - Energy in: $i^2 R t$
 - Energy req'd: ?
 - Melting requires ~ 1400 J / g for steel



Electron beam and laser welding

- Electron beam
 - Uses electrons to transfer energy
- Laser welding
 - Uses photons to transfer energy
- Pros and cons
 - Advantages: Small HAZ
 - Disadvantages: \$\$\$!, deep welds require careful fixturing




82

FUSION WELDING DEFECTS

83

Typical defects




Source: American Welding Society

84

Porosity and inclusions


- Common causes
 - Trapped gases
 - Contaminants
 - Flux particles
- Prevention
 - Pre-heat
 - Pre-cleaning
 - Improved shielding



85

Cracks in welds


- Usually result from one or combo of:
 - Temperature gradients and inability of metal to contract during cooling
- Prevention
 - Preheat components or design to minimize stress from thermal shrinking



86

Residual stresses


- Residual stresses cause problems
 - Distortion on welding
 - Reduce fatigue life
- Prevention
 - Preheating
 - Stress relieving in furnace (post heating)



87

Heat affected zone (HAZ)


- Material is not melted, but is heated
- Properties in HAZ differ and depend on:
 - Temperature
 - Time
 - Original properties
 - HI



FUSION WELDING DFM


89

DFM for Welding



90

DFM for Welding (conti.)



91

DFM for welding

- Cracks open in tension
 - Most welds are hard, not easily machined
 - Part preparation
-

92

Cost - Joining

- **Metal arc welding**
 - Low tooling costs, moderate equipment costs
 - High direct labor costs
 - Economical for low production runs
- **Resistance welding**
 - Low tooling costs, high equipment costs
 - Low direct labor costs
 - Full automation can be easily formed
- **Soldering / Brazing**
 - Low tooling costs, various equipment costs depending on the automation level
 - Low to moderate direct labor costs
- **Adhesive bonding**
 - Low tooling costs, moderate equipment costs
 - Low direct labor costs

93

Quality - Joining

- **Metal arc welding**
 - Relatively moderate HAZ exists
 - Good surface finish
- **Resistance welding**
 - Clean, high quality welding with low distortion
 - Small HAZ
 - High strength welds are produced by flash welding
- **Soldering / Brazing**
 - Virtually stress and distortion free joints
 - Excellent surface finish
- **Adhesive bonding**
 - Excellent quality joints with virtually no distortion
 - Joint strength may deteriorate with time and severe environment conditions

94

Rate - Joining

- **Metal arc welding**
 - Economical for low production runs – manual welding
 - Well suited to traversing automated and robotic systems
- **Resistance welding**
 - High production rate is possible due to short weld times
 - Easy full automation
- **Soldering / Brazing**
 - High production rates are possible for dip soldering
ex>Printed Circuit Boards
- **Adhesive bonding**
 - Low production runs

95

Flexibility - joining

- **Metal arc welding**
 - Generally high flexibility but depends on the automation level
- **Resistance welding**
 - Low flexibility due to high automation level
- **Soldering / Brazing**
 - Various level of automation is possible
- **Adhesive bonding**
 - Very flexible process
 - Can aid weight minimization in critical applications

96