

acetylene + nylons → Ethylene

Got Δ spool Time 10^2 w/cm 10^3 10^4 10^5 10^6 Fourier


Lecture: Process Planning Parameters
 activity determine procedure for final product.
 Equipment / Cost / Rate / Quality / Flexibility
 Space / People / Material

DFM
 Part size / Tolerances / Variations
 Materials / Surface quality / Shapes & complexity / Process

Heat Transfer $q_x \rightarrow \Delta T$
 $\rho C_p \frac{\partial T}{\partial t} = k \frac{\partial^2 T}{\partial x^2}$ or $\frac{\partial T}{\partial t} = \alpha \frac{\partial^2 T}{\partial x^2}$
 B.C. $T(x=x') = \text{const}$
 $-k \frac{\partial T}{\partial x}(x=x') = \text{const}$
 $-k \frac{\partial T}{\partial x}(x=x') = h(T-T_{\infty})$

Elective: Injection Molding
 C₂H₄ poly [ethylene] chains

Thermoplastic vs. Thermoset
 Amorphous Crystalline
 Cross-linked (3D-network)
 Volcanized



Pressure History Injection Mold (MPa)
 gate freeze
 Cooling time
 $t_{cool} = \frac{(R/2)^2}{\alpha}$
 $\alpha = 10^{-3} \text{ cm}^2/\text{sec}$ for polymers
 Hold Pressure (pecking) 150% injection pressure
 Clamp Force

Re # = Inertial / Viscous
 $= \frac{\rho V L}{\mu}$
 Velocity = Part length / Fill time


Non-Isothermal Flow
 Flow Rate / Heat x for Rate = $\frac{V \cdot L_z}{4 \alpha L_x}$

Total Force = Projected area x injection pressure
 ROT 4 to 5 ton/in²
 $A^2 \cdot P_{in} = F_{clump}$

Flow Path Ratio distance between gate & Fastest Point

PE	280-100	low values require large runners
PP	280-150	
PVC	280-70	
PS	300-220	

Amorphous Crystalline
 Flash
 mold quality ↑ Pinject ↑
 low viscosity ↓ Pelup ↓




Melt delivery
 Sprue / Runner / Gate / weldline
 Warpage
 inc V / Δ T


Vacuum or Pressure 14.5 to 300 psi

Short shot
 Value inject p not high
 4 Lecture Thermoforming
 Vacuum / Match Mold / Pressure / Plug assist / Free blowing

Radiative Heating absorption rate ↑
 Draw Ratio = $\frac{\text{height}}{\text{diameter}}$
 $C = \frac{D-d}{D}$
 $\frac{d}{d} = C/\theta$



Errors Effect $e = a n k$
 Production rate = r / time
 Error rate = e scrap / time
 Net profit = r - e good
 $\max_{net} \frac{dnet}{dr} = 0 = 1 - K a r^{k-1}$
 $r^{k-1} = \frac{1}{K a}$



Joining Press fit
 $F_{insert} = \mu p 2 \pi R L$
 $S_{thermal} = \alpha R \cdot \Delta T$
 Stefan equation
 $F_t = \frac{3 \mu \pi a^4}{4} \left[\frac{1}{h_f} - \frac{1}{h_i} \right]$
 low viscosity / Finish w/ high viscosity

Chip types
 1) Continuous chip - Ductile material @ high speed - Bad for automation
 2) Secondary shear zone at chip tool interface - skew zone along tool
 3) Continuous chip w/ burled up edge - High pressure working bad for automation

Assembly efficiency
 $= \frac{3^* \# \text{ theoretical Pats}}{\text{total predicted assembly time using all Pats}}$
 5% bad 30% Good
 4) serrated chip - low thermal conductivity
 5) Discontinous chip - low ductility materials & or neg rake α

Brazing $T > 450^\circ$
 Soldering $< 450^\circ$
 Covalent Bond / Vander Waals

$\alpha = 10^{-3} \text{ cm}^2/\text{s}$



Metal Cutting

$$V \frac{V_{\text{metal}}}{\text{tool}} + V \frac{V_{\text{chip}}}{\text{metal}} = V \frac{V_{\text{chip}}}{\text{tool}}$$

C → cutting S → shear
 t → thrust N → normal
 f → friction F_n → axial

Cutting Ratio

$$\frac{V_c}{V} = \frac{t_c}{t_c} = r = \frac{\sin \phi}{\cos(\phi - \alpha)}$$



$$\frac{V}{\sin(\frac{\pi}{2} - \phi + \alpha)} = \frac{V_s}{\sin(\frac{\pi}{2} - \alpha)} = \frac{V_c}{\sin(\phi)}$$

Shear plane forces

Tool-chip forces

$$F_s = F_c \cos(\phi) - F_t \sin(\phi)$$

$$F_n = F_c \sin(\phi) - F_t \cos(\phi)$$

$$F_s = F_c \sin \alpha + F_t \cos \alpha$$

$$N = F_c \cos \alpha - F_t \sin \alpha$$

$$\mu = \frac{F_s}{N} = \tan \beta$$

$$0.5 < \mu < 2$$

Analysis of shear strain

$$\phi \downarrow = \gamma \uparrow \quad \alpha \downarrow = \gamma \uparrow$$

$$\gamma = \frac{\Delta x}{A} = \frac{bc + cd}{ac}$$

$$= \cot \phi + \tan(\phi - \alpha)$$

Cutting & Thrust Forces

$$F_t = F_c \tan(\beta - \alpha)$$

$\beta < \alpha$ tool pulled in top part
 $\beta > \alpha$ tool pushed
 $\beta = \alpha$ no thrust

Merchant's minimum energy

$$\tau_s = \frac{F_s}{A_s} = \frac{F_c \cos \phi - F_t \sin \phi}{[t_c / \sin \phi] \cdot w}$$

$$\phi = \frac{\pi}{4} - \frac{\beta}{2} + \frac{\alpha}{2}$$

chip thickness

Rake & Friction ↑
 Shear ↓
 Chip thickness ↑
 Energy dissipate via shear ↑
 Heat generat ↑
 Temp ↑

Power input

$$P_{\text{machine}} \Rightarrow P_c = F_c \cdot v$$

Power dissipation

Shear = $P_s = F_s \cdot v_s$
 Friction = $P_f = F_f \cdot v_c$

Material Removal Rate

$$MRR = V \cdot t_c \cdot w$$

depth of cut

$$MRR \cdot v_c = V \cdot t_c \cdot w \cdot v_c$$

$$P_{\text{cut}} = F_c \cdot (R \omega)$$

Power & speed energy

Shear $\mu_s = \frac{F_s v_s}{w \cdot t_c \cdot v}$

Friction $\mu_f = \frac{F_f \cdot v_c}{w \cdot t_c \cdot v}$

total $\mu_t = \frac{F_c v}{w \cdot t_c \cdot v}$

Power Shear

$$F_s \cdot v_s \cdot \frac{\cos(\alpha)}{\cos(\phi - \alpha)}$$

Power Friction

$$F_f \cdot v_c \cdot \frac{\sin \phi}{\cos(\phi - \alpha)}$$

grain size $\sigma_y = \sigma_0 + \frac{K_y}{d^{1/2}}$
 Hall Petch equation

$$v_s = \frac{\tau_s}{\sin \phi} \cdot \frac{v}{V}$$

$$v_s = \tau_s \gamma$$

Forging force & Friction

$$\sigma_z = -Y \exp\left[\frac{2\mu}{h} (R-r)\right]$$

$$F_z = \pi R^2 Y \left[1 + \left(\frac{2}{3} \frac{\mu R}{h}\right)\right]$$

Steps are done for ductility of material

Tool Wear Relationship

$$V \cdot t^n = C$$

Cutting time failure velocity (min) (fpm)
 Energy $E = i^2 R \cdot t$

Propagandem of Heat for Steels $x \propto (\alpha t)^{1/2}$

Steels $n=0.1$
 Ceramics $n=0.6$

weld Pool $J_a = C_p \frac{(T_m - T_c)}{h \rho}$
 $\alpha = \frac{k}{\rho C_p}$

Melt impact $s = \sqrt{2 \alpha J_a t}$
 $V_{\text{min}} = d / t_{\text{min}}$

$$t_{\text{max}} = \frac{s_{\text{max}}^2}{2 \alpha J_a}$$

$$V_{\text{min}} = d / t_{\text{max}}$$

Power = $F_c \cdot v = MRR \cdot U$
 $F_c = \frac{MRR \cdot U}{v}$
 $MRR = F \cdot w \cdot \pi \cdot D \cdot \Omega$

$$F_c = \frac{F \cdot w \cdot \pi \cdot D \cdot \Omega \cdot U}{\pi \cdot D \cdot v} = F \cdot w \cdot U = F_c$$


$$RPM = \frac{V}{\pi D}$$

$\mu = \tan \beta$
 Friction

- Change
- Chamfers
 - Clearance Ratio
 - Friction

$$\mu_s = \frac{F_s v_s}{w \cdot t_c \cdot v}$$

Slope Stiffness



Welding force work
 Welding &

