


# Today : Injection Molding








A three-plate injection mold in (a) closed position and (b) open position. Source: *Encyclopedia of Polymer Science and Engineering*, 2d ed. Copyright © 1985. Reprinted by permission of John Wiley & Sons, Inc.

# Injection Molding Process

- Machine
- Process
- Tooling

# Melting

**Heating from the outside is difficult!**

- Conduction 
- Radiation 
- Convection 
- Internal shearing for internal heat generation!  

## **Some numbers and facts:**

- Clamp actuation can be hydraulic or electro-mechanical.
- Molds specified by shot capacity and clamping force.

Eg, 75 Ton, 6.5 ounces.

- Typical Clamping forces: 50-1,000 Tons.
- Typical Pressures: 5,000 - 40,000 psi.
- Typical temperatures: a few 200-400 °C
- Typical injection rates: 10-100 cc/sec.
- Metals (in a matrix) and thermosets can also be injection molded.


## Mold design

- Hardened steel, very high finish, abrasive resistant, chemically inert.
- Can be actuated to rotate (for threaded parts), for composite molds, for stripping and ejection.
- Must account for shrinkage, can have cooling channels.
- Use taper so that part can be extracted.
- Can have inserts.
- Tooling is very expensive. Long manufacturing lead time and usually the critical bottleneck. Sometimes molds can be huge (think rubbermaid 30 gallon), so difficult to change. i.e., Mass production!



## Rate issues and parameter selection

- Mold filling time
- Packing time
- Cooling time
- Opening/Removal/Closing time



## Molding cycle




## The processing window



## Optimizing process parameters





Increased packing time compensates for shrinkage during solidification



Increased cooling time reduced residual stresses

BUT CYCLE TIME **IS** IMPORTANT

## Weld lines



A weld is formed where the two melt zones meet, creating a v notch. The weld is weaker than the rest of the component.

The weld problem is usually alleviated by increased temperature and higher pressure. Unfortunately, this increases cycle time.

## Cooling and shrinking

- Solidification rate of a section is proportional to (thickness)<sup>2</sup>. In fact,


$$t \propto \frac{(\text{thickness})^2}{\alpha}$$

where  $\alpha$  is the thermal diffusivity of the material, given by


$$\alpha = \frac{k}{\rho C_p}.$$

- 
- Shrinkage occurs during solidification and during cooling.
    - Solidification shrinkage can be reduced by increased packing time
    - Temperature shrinkage controlled by larger mold size.


## Shrinkage issues





Flow based alignment



## Strength issues





The molecules align in the major direction of flow, and hence there is greater strength.



## DFM


- Ribs to avoid warpage and to strengthen flat sections.
- Gate location(s) must:
  - minimize polymer travel
  - increase symmetry
  - Prevent air entrapment
- Line up flow lines with maximum strength requirements (eg. handle in lunch box)
- Avoid welds in critical areas.
- Account for shrinkage, part removal.

## Examples of DFM




Compensating for swell

Poor Design



Improved Design






Fig. 9-15. This sketch illustrates many features of a well-designed part and points out problem areas. (Courtesy Marbon Div Borg Warner Corp., Washington, W. Va.)