

# LEAN MANUFACTURING


Sanjay Sarma

2

# Variations

# Propagation of Variability

3



# Variability Makes a Difference!

4

- Little's Law:  $TH = WIP/CT$ , so same throughput can be obtained with large WIP, long CT or small WIP, short CT. The difference? *Variability!*
- Penny Fab One: achieves full TH (0.5 j/hr) at  $WIP = W_0 = 4$  jobs if it behaves like Best Case, but requires  $WIP = 57$  jobs to achieve 95% of capacity if it behaves like the Practical Worst Case. Why? *Variability!*

# Measuring Process Variability

5

$\bar{t}$  = mean

$\sigma$  = standard deviation

$c = \frac{\sigma}{\bar{t}}$  = coefficient of variation, CV

$c^2 = \frac{\sigma^2}{\bar{t}^2}$  = squared coefficient of variation, SCV

# Variability Classes

6

Variability Class	Coefficient of Variation	Typical Situation
Low (LV)	$c < 0.75$	Process times without outages
Moderate (MV)	$0.75 \leq c \leq 1.33$	Process times with short adjustments (e.g., setups)
High (HV)	$c \geq 1.33$	Process times with long outages (e.g., failures)

# Natural Variability

7

- **Definition:** variability without explicitly analyzed cause, variability inherent in natural process time.
  
- **Sources:**
  - ▣ operator pace
  - ▣ material fluctuations
  - ▣ product type (if not explicitly considered)
  - ▣ product quality
  
- **Observation:** Natural process variability is usually in the LV category.

# Machine Downtimes

8

- **Preemptive outages:** downtimes that occur whether we want them to or not (e.g., they can occur right in the middle of a job).
  - ▣ Examples: machine breakdowns, power outages,..
  
- **Nonpreemptive outages:** downtimes that will inevitably occur but for which we have some control as to exactly when.
  - ▣ Example: process changeovers (setups)

# Down Time – Mean Effects

9

## Definitions:

$t_0$  = mean of natural process time

$\sigma_0$  = standard deviation of natural process time

$c_0$  = coefficient of variability of natural process time

$r_0$  = natural capacity (rate)

$m_f$  = mean time to failure (MTTF)

$m_r$  = mean time to repair (MTTR)

$\sigma_r$  = standard deviation of repair time

$c_r$  = coefficient of variability of repair time,  $c_r = \frac{\sigma_r}{m_r}$

# Down Time – Mean Effects (cont.)

10

Availability: Fraction of time machine is up

$$A = \frac{m_f}{m_f + m_r}$$

Effective mean process time:  $t_e = \frac{t_0}{A}$


Effective capacity (rate):  $r_e = \frac{1}{t_e} = Ar_0$

$m$  = number of machines


# Flow Variability

11

## Low variability arrivals



## High variability arrivals



# Measuring Flow Variability

12

$t_a$  = mean time between arrivals

$r_a$  = average arrival rate

$\sigma_a$  = standard deviation of the time between arrivals

$c_a$  = CV of interarrival time

$$r_a = \frac{1}{t_a}$$

$t_d$  = mean time between departures


$r_d$  = average departure rate

$c_d$  = departure CV

$$c_a = \frac{\sigma_a}{t_a}$$

# Propagation of Variability

13



# Characterizing Variability in Flows

14

- **Utilization** : fraction of time a workstation is busy over the long run..

$u$ : utilization of a workstation consisting of  $m$  identical machines


$$u = \frac{r_a t_e}{m} = \frac{r_a}{r_e}$$

$$0 < u < 1 \quad \Rightarrow \quad r_e > r_a$$

**Single Machine Station:**  $c_d^2 = u^2 c_e^2 + (1 - u^2) c_a^2$

# High Utilization Station


15



**Conclusion:** *flow variability out of a high utilization station is determined primarily by process variability at that station.*

# Low Utilization Station

16



***Conclusion:** flow variability out of a low utilization station is determined primarily by flow variability into that station.*

# Average queue length

17

## □ Formula:

$$CT_q \approx \underbrace{\left( \frac{c_a^2 + c_e^2}{2} \right)}_V \underbrace{\left( \frac{u}{1-u} \right)}_U \underbrace{t_e}_T$$

## □ Observations:

- $CT = CT_q + t_e$
- Refer to as Kingman's equation or *VUT* equation.
- Separate terms for variability, utilization, process time.
- $CT_q$  (and other measures) increase with  $c_a^2$  and  $c_e^2$ .
- *Variability causes congestion!*

# Example

18

## Hare X19:

$$t_e = 20 \text{ minutes}$$

$$c_e^2 = 6.25$$

$$c_a^2 = 1.0$$

$$u = 0.9583$$

$$\begin{aligned} CT_q &= \left( \frac{c_a^2 + c_e^2}{2} \right) \left( \frac{u}{1-u} \right) t_e = \left( \frac{1 + 6.25}{2} \right) \left( \frac{0.9583}{1 - 0.9583} \right) 20 \\ &= 1,667.5 \text{ minutes} = 27.79 \text{ hours} \end{aligned}$$

$$\begin{aligned} c_d^2 &= c_e^2 u^2 + c_a^2 (1 - u^2) = 6.25(0.9583^2) + 1.0(1 - 0.9583^2) \\ &= 5.8216 \end{aligned}$$


# The G/G/1 Queue — Example

19

Assume the Hare feeds the Tortoise, then  $c_a^2$  for the Tortoise is equal to  $c_d^2$  for the Hare.

The expected queue time at the Tortoise:

$$\begin{aligned} CT_q &= \left( \frac{c_a^2 + c_e^2}{2} \right) \left( \frac{u}{1-u} \right) t_e = \left( \frac{5.82 + 1.0}{2} \right) \left( \frac{0.9583}{1-0.9583} \right) 20 \\ &= 1,568.97 \text{ minutes} = 26.15 \text{ hours} \end{aligned}$$



# Conclusions

20






- Variability is a fact of life.
- There are many sources of variability in manufacturing systems.
- The coefficient of variation is a key measure of item variability.
- Variability propagates.
- Waiting time is frequently the largest component of cycle time.
- Limiting buffers reduces cycle time at the cost of decreasing throughput.
- Variability pooling reduces the effect of variability.

21

# Lean Manufacturing

# Plant layout

22




# Performance Measures

23


- Capital cost
- Production rate or capacity
- Cycle time
- Lead time
- Machine utilization
- Work-in-process
- On-time deliveries

# Where the Time Goes In Mid-Volume Metalworking


24



# By production methods,...



Type of Production		
Job shop	Batch production	Mass production



# Complexity

26

## Product complexity


product	Number of components
Mechanical pencil	10
Rifle	50
Sewing machine	150
Bicycle	750
Automobile	20,000
Commercial airplane	1,000,000
Space shuttle	10,000,000

## Part complexity

part	Number of operations	Typical operations
Injection molded part	1	Molding
Washer(steel)	1	Stamping
Washer(plated)	2	Stamping, electroplating
Pump shaft	10	Machining
Coated carbide tool	15	Pressing, sintering, coating, grinding
Pump housing	20	Casting, machining
V-6 engine block	50	Casting, machining
IC chip	75-100	CVD, PVD, photolithography, etching, packaging

# Types of automation

27



# Transfer Line

28





Figure 38.5 A large transfer line for producing engine blocks and cylinder heads. *Source:* Ford Motor Company.


# Cell Manufacturing

29



# U-cell production

30



## A woodworking assembly cell

- This is an assembly and packaging line for wooden doors.
- There is no in-process inventory within the cell.
- The workers perform multi-process handling.
- To reduce the number of operators, machines have been equipped with *jidoka* or automation with a human touch. The machines can complete the cycle initiated by the operators.
- Unlike the traditional batch system, doors are processed one at a time. This requires less space.

# Improving Material Flow

31

## Cellular Manufacturing

### □ Benefits

- Reduce MLT (Mfg Lead Time) normally 75%
- Reduce footprint
- Improve quality, productivity, visibility


### □ Challenges

- Less machine utilization
- Vulnerability to machine failures

# Manufacturing operations

32


- Processing and assembly
- Material handling
- Inspection and test
- Coordination and control




# Production Line Control

33

**Production Line Output Variability**





Machines are unreliable  
Buffers are finite  
Average production rate  
Average inventory



# Toyota Manufacturing System

34



# TPS: Features & Elements

35

- Fast response, flexibility
- Product variety
- Production schedule stability
- Supply/chain integration
- SMED (Fast Die Change)
- Highlighting problems
- Gradual elimination of waste
  - ▣ Continuous
  - ▣ Root cause analysis
  - ▣ Fool proofing remedy
- Worker training
- **Just-in-Time** production
- Stable production schedules

**Value:** Would someone pay for this? If no, then it's **Waste**.

# Lean Manufacturing

36

- Identifying and eliminating non-value-added effort, resources and wastes of
  - Overproduction
  - Waiting time
  - Transportation
  - Processing
  - Inventory
  - Motion
  - Defects

# The ten rules of lean production


37

1. Eliminate waste
2. Minimize inventory
3. Maximize flow
4. Pull production from customer demand
5. Meet customer requirements
6. Do it right the first time
7. Empower workers
8. Design for rapid changeover
9. Partner with suppliers
10. Create a culture of continuous improvement


# You've seen this before.

38

Temporary storage of wire harnesses: Is it really temporary? When will these quasi products be moved?



Temporary storage



Defect storage

Storage for wire harness defectives: Profits are impossible with so many defectives.

# Visual Control

39



02

# JIT (Just-in-time)

40

Produce only what is needed, when is needed in just the amount needed.

Material → Parts → sub-assemblies → finished goods → customers

- Inventory
- Defects
- Large Lot
- Rising Cost
- Delivery Delays

# The Seven Zeros

41

- Zero Defects: **To avoid delays due to defects. (Quality at the source)**
- Zero (Excess) Lot Size: **To avoid “waiting inventory” delays. (Usually stated as a *lot size of one.*)**
- Zero Setups: **To minimize setup delay and facilitate small lot sizes.**
- Zero Breakdowns: **To avoid stopping tightly coupled line.**
- Zero (Excess) Handling: **To promote flow of parts.**
- Zero Lead Time: **To ensure rapid replenishment of parts (very close to the core of the zero inventories objective).**
- Zero Surging (sudden changes): **Necessary in system without WIP buffers.**


# JIT implementation

42

- Awareness revolution
- Workplace improvements
  - ▣ Cleanliness, orderliness, discipline
- Visual control
- Flow manufacturing
- Quality assurance
- Standard operation


# Traditional “Buffered” Supply Chain

43




# The Just-in-Time :No Stocks!

44




## Push vs. Pull

**Make all we can  
just in case.**



- Production Approximation
- Anticipated Usage's
- Large Lots
- High Inventories
- Waste
- Management by Firefighting
- Poor Communication

**Make what's needed  
when we need it**





- Production Precision
- Actual Consumption
- Small Lots
- Low Inventories
- Waste Reduction
- Management by Sight
- Better Communication


# Push vs. Pull

46

## PUSH SYSTEMS VS. PULL SYSTEMS FOR PRODUCTION PLANNING AND CONTROL



(“Manufacturing in the Nineties” by Steudel and Desruelle, pp. 238-239)




(From “The New Manufacturing Challenge” by K. Suzuki, pp. 149)

# Kanban system

47

## Two Kanbans

- Production card
- Move card




(From "The New Manufacturing Challenge" by K. Suzuki, pp. 151)



# Kanban system

48

## Two Kanbans

- Production card
- Move card





# Global Manufacturing Environment

50

- Customers want:
  - Innovation
  - quality and reliability, and
  - they want it **NOW!**
- Competitive firms have to deliver products:
  - that both sell and are produced globally,
  - using a work force with different experience and training, and
  - do it **QUICKLY!**

All in all, firms should produce good products that best satisfy customers while maximizing the value creation.