



Design → Finished part

Word processing



Manufacturing



Today

1. CAD

- What it isnt.
- Boundary Representation
- Solid Modeling
- Surface Modeling


2. CAM

- Tool Path Generation
- Zig-zag
- Surface Machining
- Features
- Contour Shrinking

3. CNC

- How CNC works
- M Codes
- G Codes

CAD



How to represent solid shapes?

- Constructive Solid Geometry

describe parts by assembling primitive shapes such as blocks, cones and spheres.

- Boundary representation

describe parts by specifying the skin of the required shape as a series of faces bounded by edges bounded by vertices.

- Space Enumeration

build parts with cubical bricks. its like building the shape from 3-d pixels.

The solid modeling engine

this is the core of every CAD system. it's main functions are:

- point solid classification
- solid-solid interaction
- visualization
- mass and area properties
- generating meshes for finite element analysis

Constructive solid geometry

the designer gives a palette of shape primitives:

examples: a cube, a cylinder, a taurus, a sphere.

Scale parametrically and use boolean operations:

- union
- subtraction
- intersection

to create shapes.

examples:

addition of two cubes, intersection of two cubes, etc.

Boundary representation

remove everything from the inside and represent the skin as a patchwork, or quilt, of surfaces.

ex: a cube is represented as six plane surfaces.

a cylinder would be represented as the cylindrical surface, plus two circular planes at the ends.

Each smooth surface, meanwhile, can be represented with equations. for ex:

$$z = x + y$$

represents a plane. How would you represent a sphere?

Boundary representation

Euler's rule for solids:

$$V - E + F = 2$$

for ex:

cube: $V=8$, $E=12$, $F=6$

tetrahedron: $V=4$, $E=6$, $F=4$

octahedron: $V=6$, $E=12$, $F=8$

- boundary representation is the most elaborate and robust solid modeling technique

- it is the most widely used approach commercially:


Parasolids, ACIS, AutoCAD, ProEngineer, Intergraph, SDRC, etc.

- computation intensive.

Surfaces

A surface is a 2-D entity

If is parametrised with 2 parameters,



Simple bicubic patch

$$\tilde{p}(u,v) = \sum_{i=0}^3 \sum_{j=0}^3 \tilde{a}_{ij} u^i v^j$$


$$u, v \in [0,1]$$

Where \tilde{p} is a point on the patch,
 u, v are parameters,
 & \tilde{a}_{ij} are algebraic coefficients.

— x —

$$\begin{aligned} \tilde{p}(u,v) = & a_{33} u^3 v^3 + a_{32} u^3 v^2 + a_{31} u^3 v + a_{30} u^3 \\ & + a_{23} u^2 v^3 + a_{22} u^2 v^2 + a_{21} u^2 v + a_{20} u^2 \\ & + a_{13} u v^3 + a_{12} u v^2 + a_{11} u v + a_{10} u \\ & + a_{03} v^3 + a_{02} v^2 + a_{01} v + a_{00} \end{aligned}$$

CAD and machining:




CAM : Computer Aided Manufacturing

- Should really be : Computer Assisted Tool Path Generation
- Given primitive shapes, a CAM program will generate sweeping tool paths.
- Modes:
 - 2 1/2 D
 - 3 Axis Surface
 - 5 Axis Surface

2 1/2 D Machining


Machining of 2-D contours with depth:



Organize shape in terms of slabs.

Stages in Machining

- Roughing : Heavy Cut, Gross Removal
- Finishing : Fine Cut, Delicate Removal




Pitfalls


VERTICAL ACCESS NOT CONSIDERED




CUSPS




GOUGING



3 Axis Surface Machining




Offsets in 3-Axis




5-Axis Machining

Surface Normal

Drive Surface



Tangents?



AN ORTHOGONAL NET
OF ISOPARAMETRIC CURVES

When tool paths are done . . .

output of CAM program

- centerline data

centerline --->post processor ---->Machine Path

