


## Today & Monday: Joining and Assembly

- Parts handling & Mechanical assembly
- Joining processes:
  - Mechanical joining
  - Soldering & Brazing
  - Gluing
  - **Welding (Several sub areas)**
- Design for Assembly

# Manufacture



## Joining assembly

- Study the chairs you are sitting on. How many unit components, and how were they joined?
  - geometry
  - material
  - size
  - value of product
  - quality
  - strength
  - size of run
  - Availability

---

**Cost:** 

Expensive \$100.00 — \$10,000.00

**Flexibility:** 

Any shape under the sun!

**Quality:** 


Very high quality.

**Rate:** 


Slow compared to other production techniques.

## Statistics: How important is assembly?

Industry	% Workers in Assembly
Automobile	45.6%
Aircraft	25.6%
Telephone & Telegraph	58.9%
Farm Machinery	20.1%
Home appliances	32.1%
Two-wheel vehicles	26.3%



## Classification of joining processes





## Parts Handling

- Part feeding
- Part orienting
- Part transfer


## Feeding:

- Spacing and frequency of supply to a machine
- Control of amount or number
- Disentanglement
- Methods:
  - Vibratory Bowl Feeders
  - Magnetic
  - Pneumatic









(a)




(b)






$\alpha$	0	180	180	90	360
$\beta$	0	0	90	180	360


# Mechanized Part Orienting



(a) Washer accepted



(b) Washer rejected



## **Mechanized part transfer**


- transfer line
- conveyor
- overhead transport
- automated guided vehicle

# Conveyors


Types:

- belt
- chain
- roller

With conveyors, material is often held in palettes or totes. These serve to organize the parts and allow a given conveyor to transport a wide variety of sizes and shapes, making it more flexible.



## Transfer Lines




classic example :  
machining an automotive  
engine block, 100-200  
stations

Hard Automation - not very  
flexible.

A "true" transfer line is  
shown here:

## AGV

Schematic illustration of an automated guided vehicle [AGV], showing two different workpieces on pallets. [source: P. Ranky]



## Overhead Transport

- usually runs on “I” beams.
- can be self powered or driven
- Often can be used for large items - auto bodies




Fig. 9.6.1 Power-and-free trolleys queued at a stop.





Fig. 9.6.8 Typical power-and-free cross section.

## Work Envelopes

for three types of robots. The choice depends on the particular application.



# Robots

Definition I : Emulates a human being.

- has intelligence
- can manipulate in space

Definition II : Is a mechanical manipulation device

- programmable
- wide range of motion

# Components

## 1. Manipulator


- positioning
- power
- stiffness
- control

## 2. End Effector

- tooling

## Components of a typical industrial robot

[source : Cincinnati Milacron, Inc.]




## **Joining: Mechanical fastening**

- Rivets
- Nuts-Bolt
- Screw-Tapping
- Press fits
- Mechanical locks

## **Solid-Liquid Joining: Adhesives**


- Quick, non-invasive, inexpensive
- Quality questionable, rate depends on technology
- Extremely good for home applications and non-critical components  
such as
- Technologies:
  - Water or oil soluble
  - Thermoplastic or thermoset
  - Chemical set (epoxy glues)

## Adhesives: physics



- Bonds created by filling hills and valleys
- Best for components with high surface to volume ratio:  
sheets, fibres, small particles
- Dominant physics:
  - Viscosity  $\leftarrow$  Stefan's Law
  - Surface Tension
  - Phase Transformation

## How long to squeeze drop?



Velocity profile:  $u = \frac{1}{2\mu} \frac{dP}{dr} \left\{ y^2 - \frac{h^2}{4} \right\}$  — I

Volume flowrate at  $r$ :

$$\int_{-h/2}^{h/2} u \cdot 2\pi r \cdot dy = -\pi r^2 \frac{dh}{dt}$$

— II

Rearranging:

$$\frac{dP}{dr} = \frac{6\mu}{h^3} \cdot \frac{dh}{dt} \cdot r$$

$$\Rightarrow P = \frac{6\mu}{h^3} \frac{dh}{dt} \frac{r^2}{2} + C$$

B.C:  $P=0$  @  $r=a$

$$\rightarrow C = - \frac{3\mu a^2}{h^3} \frac{dh}{dt}$$

$\therefore$

$$P = \frac{3\mu}{h^3} \cdot \frac{dh}{dt} (r^2 - a^2)$$

## How long to squeeze a drop?

$$P = \frac{3\mu}{h^3} \frac{dh}{dt} (r^2 - a^2)$$

Force balance:

$$F = \int_0^a P \cdot 2\pi r \cdot dr$$

$$\therefore F = -\frac{3\mu\pi a^4}{2h^3} \cdot \frac{dh}{dt}$$



$$dF = P \cdot 2\pi r \cdot dr$$

Integrating from  $t: 0 \text{ to } t$   
 $h: h_i \text{ to } h_f$

$$\int_0^t F \cdot dt = \int_{h_i}^{h_f} -\frac{3\mu\pi a^4}{2} \frac{dh}{h^3}$$

$$\therefore Ft = \frac{3\mu\pi a^4}{4} \left[ \frac{1}{h_f^2} - \frac{1}{h_i^2} \right]$$

STEFAN'S  
EQUATION

$$Ft = \frac{3\mu\pi a^4}{4} \cdot \frac{1}{h_f^2}$$

## Stefan's Equation

What's the point?

- valid for separation


$$Ft = \frac{3\mu\pi a^3}{4} \cdot \frac{1}{h_f^2}$$

for constant time :

$h_f \downarrow$	$\rightarrow$	$F \uparrow$
$\mu \uparrow$	$\rightarrow$	$F \uparrow$

Basic Idea in Adhesion:

- start with low viscosity



- reduce gap

- increase viscosity

Adhesion complete.


## Solid-Liquid Joining: Soldering & Brazing

- Substrate phase stays **solid!** Can be used on dissimilar metals.
- Filler phase is melted, less than 700°C
- Soldering: <425°C: Lead, Tin, Bismuth, Cadmium
- Brazing: >425°C: Silver, Brass, Bronze
- Used in electronics, plumbing, jewelry, and recently, as a structural joining technique.

## Physics:

- Phase change of solder or braze
- Surface tension, low viscosity = capillary action, improved wetting
- Intermetallic compounds may be formed. They are brittle.
- Problems:
  - Oxides prevent good diffusion and cohesion  
(1-3 oxide monolayers in  $10^{-14}$  s with 1 atm pressure)
  - CTE mismatch can cause problems
  - Fracture, fatigue, creep problems, porosity

## Mechanism of flux shielded soldering or brazing




- A. flux over oxidized metal
- B. boiling flux removes oxide
- C. base metal in contact with molten flux
- D. molten solder displaces molten flux
- E. solder alloys with base metal
- F. solder solidifies

<--- direction of movement of soldering iron

## Influence of halide content


[measured as chlorine] of rosin base activated fluxes on solderability of clean and oxidised copper using 60% tin 40% lead solder at 250 deg. C.



## Shear strength vs brazed joint thickness

for pure silver joints in 12.7 mm [0.5 in] diameter steel drill rod.

Creep: > 1000 psi @ 0.75 Tm. make joints thin.



## Fluxes


- Essential in soldering, lower temperatures
  - Rosen is an organic material, most common.  
Sometimes contains chlorine for reducing quality.
- Fluxes have three functions:
  - Oxide removal (not required in brazing)
  - Coating to prevent further oxidation
  - Improved surface wetting
- Fluxes usually come in a delivery agent: waxy, oil, grease.

## **System Performance of Soldering and Brazing**

- Very cheap.
- Automatable, hence reasonable rates. Wave soldering machines.
- Reasonable strength, but no surface damage. So Quality OK. Highly conductive.
- Machinery not very flexible.

# DFA

solder and braze:



ADHESIVES :

