Slow Control / Vacuum / Target

Jan C. Bernauer



Collaboration Meeting April 2012



Massachusetts Institute of Technology

1

- Single system, controls (almost) everything
- Overview + control via web



- Single system, controls (almost) everything
- Overview + control via web
- Stable? operation
 - new features
 - small bugs



- Single system, controls (almost) everything
- Overview + control via web
- Stable? operation
 - new features
 - small bugs

 Implemented alarm gateway to TINE (for DESY operators).



- Single system, controls (almost) everything
- Overview + control via web
- Stable? operation
 - new features
 - small bugs

- Implemented alarm gateway to TINE (for DESY operators).
- Will release software as open source.



- Single system, controls (almost) everything
- Overview + control via web
- Stable? operation
 - new features
 - small bugs

- Implemented alarm gateway to TINE (for DESY operators).
- Will release software as open source.
- Wishes?



Target vacuum system

No problems during run.

Target vacuum system

- No problems during run.
- One pump died during synchrotron operation
 - Did not trip HW-interlock (pressure too good).
 - Noticed by bad beam lifetime.
 - Fix: Close valve.
 - Added second level SW-interlock.
- Pump will be replaced in June service week.

Target

- Temperatures were <50K, good.
- Flows up to 1 sccm were tested.
- 0.8 sccm most of the time, with beam lifetime O(1h).

Target

- Temperatures were <50K, good.
- Flows up to 1 sccm were tested.
- 0.8 sccm most of the time, with beam lifetime O(1h).

All Good?

- During beamtime: Countrate estimates higher than observed rates
 - But factors varied greatly: 2-20

- During beamtime: Countrate estimates higher than observed rates
 - But factors varied greatly: 2-20
- Now: Somewhat clearer picture, but still no hard numbers?!?!
 - Factor seems to be 4-6?

- During beamtime: Countrate estimates higher than observed rates
 - But factors varied greatly: 2-20
- Now: Somewhat clearer picture, but still no hard numbers?!?!
 - Factor seems to be 4-6?
- Possible causes?
 - ullet Beam current wrong? \longrightarrow Unlikely.

- During beamtime: Countrate estimates higher than observed rates
 - But factors varied greatly: 2-20
- Now: Somewhat clearer picture, but still no hard numbers?!?!
 - Factor seems to be 4-6?
- Possible causes?
 - ullet Beam current wrong? \longrightarrow Unlikely.
 - \bullet Target flow wrong? \longrightarrow Calibrated with buffer volume.

- During beamtime: Countrate estimates higher than observed rates
 - But factors varied greatly: 2-20
- Now: Somewhat clearer picture, but still no hard numbers?!?!
 - Factor seems to be 4-6?
- Possible causes?
 - ullet Beam current wrong? \longrightarrow Unlikely.
 - Target flow wrong? → Calibrated with buffer volume.
 - Target density calculation wrong?

 Checked idenpendently

- During beamtime: Countrate estimates higher than observed rates
 - But factors varied greatly: 2-20
- Now: Somewhat clearer picture, but still no hard numbers?!?!
 - Factor seems to be 4-6?
- Possible causes?
 - ullet Beam current wrong? \longrightarrow Unlikely.
 - Target flow wrong?
 — Calibrated with buffer volume.
 - Target density calculation wrong? Checked idenpendently
 - Countrate estimates wrong?

 Different calculations give similar answer.

- Lifetime about factor 2 too good compared to TDR.
 - But how accurate is the calculation?
 - (Lifetime could be worsened by impurities in gas -> check next week)

- Lifetime about factor 2 too good compared to TDR.
 - But how accurate is the calculation?
 - (Lifetime could be worsened by impurities in gas -> check next week)
- Out of molecular flow? → Test with extreme low flows
 → Only small deviation.

- Lifetime about factor 2 too good compared to TDR.
 - But how accurate is the calculation?
 - (Lifetime could be worsened by impurities in gas -> check next week)
- Out of molecular flow? → Test with extreme low flows
 → Only small deviation.
- Extreme gas heating? How? Can be tested with heater on cell.

- Lifetime about factor 2 too good compared to TDR.
 - But how accurate is the calculation?
 - (Lifetime could be worsened by impurities in gas -> check next week)
- Out of molecular flow? → Test with extreme low flows
 → Only small deviation.
- Extreme gas heating? How? Can be tested with heater on cell.
- Gas "lost" inside vacuum chamber.
 - Not visible on pressure readings.

Leak?

- Inspection of replacement cells
 - One likely candidate: Connection between cell inlet formed by foil and aluminium bracket.
- Will inspect and try to fix in June service week

