

Example 2.6 Select a single angle to support a tensile load. Live and dead loads are 50 kips and 25 kips, respectively. A single gage line of three $1\frac{7}{8}$ -in. bolts is to be used and the length of the angle made of A36 steel is 20-ft.

