

Example 7.6 An angle must carry a 95 kips live load and a 40 kips dead load. Select the highest $L6 \times 4$ angle with bolts connected on one leg only. Use $3/4$ -in. dia. A325-X bolts and A36 angle.