

Example 7.4 How many 3/4-in. A325X bolts are required for the bearing-type connection shown below? Assume $L_e > 1.5d$ and $s > 3d$. Use A36 steel. The deformation around the hole is a design consideration.

