





# Pugh charts

assessment criteria

benchmark idea

rate. +, S, or -

relative to benchmark

	NAIL 	RING SHANK 	STAPLE 	SCREW 
RATE	S	S	+	-
COST	S	-	+	-
HOLDING	S	+	-	+++
EFFORT	S	S	+	-

